

TRIANGLE ENVIRONMENTAL

175 Metro Center Blvd.
WARWICK, RHODE ISLAND 02886

LETTER OF TRANSMITTAL

(401) 737-0570

TO DAVID SHELDON
DIV OF GROUNDWATER
DEM

DATE <u>29 JUNE 92</u>	JOB NO.
ATTENTION <u>DAVE S</u>	
RE: <u>100 BOSWORTH ST</u> <u>PROVIDENCE RI</u> <u>LEAKING TANK ENFORCEMENT</u> <u>CASE LS 283C</u>	

WE ARE SENDING YOU ☒ Attached ☐ Under separate cover via _____ the following items:

- ☐ Shop drawings ☐ Prints ☐ Plans ☐ Samples ☐ Specifications
☐ Copy of letter ☐ Change order ☒ Like

COPIES	DATE	NO.	DESCRIPTION
1	June 29, 92		June 29 Letter RE: THE ABOVE MENTIONED SITE

THESE ARE TRANSMITTED as checked below:

- ☒ For approval ☐ Approved as submitted ☐ Resubmit _____ copies for approval
☒ For your use ☐ Approved as noted ☐ Submit _____ copies for distribution
☒ As requested ☐ Returned for corrections ☐ Return _____ corrected prints
☒ For review and comment ☐ _____

☐ FOR BIDS DUE _____ 19____ ☐ PRINTS RETURNED AFTER LOAN TO US

REMARKS DAVE - ATTACHED IS LETTER RESPONDING TO your
26 May 1992 letter to Piero Maggiasano. Call
me if you have any questions

COPY TO _____

SIGNED: Sincerely
[Signature]

TRIANGLE ENGINEERING
175 METRO CENTER BOULEVARD
WARWICK, RI. 02886
(401) 737-0570

June 29, 1992

Mr. David Sheldon CPG, Senior Engineer
Leaking Tank Enforcement Program
Division Of Water Resources
Department Of Environmental Management
291 Promenade Street
Providence, R.I.

Re: Property located on 100 Bosworth Street
Providence, R.I.
Leaking Tank Enforcement Case LS 2836

Dear David:


This letter is in response to your letter dated 26 May 1992 to Mr. Piero Maggiacomo regarding the above mentioned site. Your letter stated that 3 (three) items needed to be addressed within 30 days of receipt of your letter. The following responses are in the same order as they were presented in your 26 May 1992 letter:

1. Mr Maggiacomo has informed Triangle Environmental that all related piping to the existing 10,000 gallon underground storage tank will be removed and capped at the tank. The tank will then be precision tested. The precision test will be completed within 2 (two) weeks. Your office will be notified of the date of precision testing.
2. After further review of the subject property it appears that there is a second underground storage tank in the vicinity of the aforementioned 10,000 gallon tank. The piping for the 10,000 gallon underground storage tank, which will be removed, also appears to be above the second underground storage tank. During excavation of the underground piping, the location and size of the second tank can be exposed. At that time any other exploratory work around the tank will be discussed. This work will be performed prior to the precision testing of the 10,000 gallon tank. Your office will be notified of the excavation work so that a representative from your office may be present if necessary.
3. As you may already be aware, Triangle Engineering has been retained to provide their services for further investigation work on the subject property.

Triangle Environmental
June 29, 1992

If you should have an question regarding the contents of this letter please contact me at 737-0570.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael A. Del Rossi". The signature is fluid and cursive, with a large loop at the end.

Michael A. Del Rossi, P.E.
Partner

cc: Piero Maggiacomo