

TRIANGLE ENVIRONMENTAL

175 Metro Center Blvd.
WARWICK, RHODE ISLAND 02886

LETTER OF TRANSMITTAL

(401) 737-0570

TO DAVE SHELTON

DATE	21 Aug 92	JOB NO.
ATTENTION	DAVE SHELTON	
RE:	100 BOSWORTH ST PROVIDENCE, R.I. LEAKING TANK CHIG LS283C UST EXEMPTION	

AUG 21 1992

WE ARE SENDING YOU ☐ Attached ☐ Under separate cover via _____ the following items:

- ☐ Shop drawings ☐ Prints ☐ Plans ☐ Samples ☐ Specifications
☒ Copy of letter ☐ Change order ☐ _____

COPIES	DATE	NO.	DESCRIPTION
1	AUG 19, 92		Letter on UST EXEMPTION

THESE ARE TRANSMITTED as checked below:

- ☒ For approval ☐ Approved as submitted ☐ Resubmit _____ copies for approval
☒ For your use ☐ Approved as noted ☐ Submit _____ copies for distribution
☐ As requested ☐ Returned for corrections ☐ Return _____ corrected prints
☒ For review and comment ☐ _____
☐ FOR BIDS DUE _____ 19____ ☐ PRINTS RETURNED AFTER LOAN TO US

REMARKS DAVE - Attached is Correspondence For A UST

EXEMPTION For THE ABOVE MENTIONED Project. IF

you SHOULD HAVE ANY QUESTIONS PLEASE CONTACT

Me @ 737-0570

COPY TO _____

SIGNED: Sincerely
Michael R



August 19, 1992

Mr. David Sheldon CPG, Senior Engineer
Leaking Tank Enforcement Program
Division of Water Resources
Department of Environmental Management
291 Promenade Street
Providence, RI

Re: Property located on 100 Bosworth Street
Providence, RI
Leaking Tank Enforcement Case LS 2836
UST Exemption

Dear David:

Please accept this letter as a request for a variance of the precision testing an underground storage tank under Section 19.01 Variances of the State of Rhode Island Regulations For Underground storage Facilities, Used For Petroleum Products and Hazardous Material dated June 1992. The specific request for variance is listed under Section 15.12 (A) UST Closure in Place. This portion of the section requires that a precision test be performed and tested tight prior to filling the tank with an inert solid material.

The above request for variance is based on the location of a 15,000 gallon underground storage tank at the above referenced location. A portion of the tank was exposed during the morning of August 17, 1992. That same afternoon the undersigned visited the site to observe the location of the underground tank. The northwest portion of the tank was exposed as well as the piping coming from the center of the tank. According to the information obtained from the owner of the property the tank's dimensions are 10' - 6" in diameter and 23' - 2" long. The tank sits parallel to an adjacent retaining wall which abuts Star Tron Inc. The center of the tank is approximately 8' - 10' from the retaining wall or the edge of the tank approximately 4' from the wall. It is my opinion that if this tank is to be removed, the structural integrity of the wall and adjacent building may be affected.

TRIANGLE ENVIRONMENTAL
August 19, 1992

We request that a qualified underground storage tank contractor remove a top portion of the tank and have the remaining contents removed. Once the product has been removed the tank will be filled with an inert material. Attached is the contractors assessment of the possible damages that may result if the tank were to be removed.

Please contact this office if a field visit is required to review the above stated condition. If you should have any questions regarding this variance, please contact this office at 737-0570. In the meantime, I will be awaiting your response to this variance.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael A. Del Rossi". The signature is fluid and cursive, with the first name "Michael" and last name "Del Rossi" clearly distinguishable.

Michael A. Del Rossi, P.E.
Partner

cc: Piero Maggiasco